


Select energy efficient refrigerators listed below are eligible for New Jersey's Clean Energy Program \$50 or \$75 rebate. Following each brand, qualifying model numbers appear below/following the dollar amounts shown. Asterisks (\*) represent any character, letter or number. Number signs (#) represent any number. Please contact us at 866-NJSMART (657-6278) if you would like to confirm the model you are considering purchasing is eligible for an incentive.

List as of June 26, 2018

<b>Absocold</b>	<b>Beko</b>	BRFB1812SS	B30B8830SS	CRMH184PB	DFF103A4WDBL	ERTM180WE	RS36W(X)	FFHT1514Q*	FGHS2355P**B	RC462701
<b>\$50</b>	<b>\$50</b>	BRFB1812SSL	B30B8800SP	CRMH184PS	DFF180E1*	<b>Emerald Chef</b>	<b>Fisher &amp; Paykel</b>	FFHT1514T*	FGHS2631P**A	RC462704
ARD1033F*14R/L	BBBF2410IM	BRFB1812SSLN	B36BT830NS	CRMH184PW	<b>Danby Designer</b>	<b>\$50</b>	<b>\$50</b>	FFHT1521Q*	FGHS2655P**A	RC472701
<b>Amana</b>	BFBF2413SS	BRFB1812SSN	B36BT930NS	CRT10PHS2	<b>\$50</b>	RF 2105B	RB2470BRV1	FFHT1614Q*	FGHS2655P**B	RC472704
<b>\$50</b>	BFBF2413SSIM	BRFB1822SSLN	B36IT800NP	CRT10PHW2	DAR110A1*	RF 2105SS	RF170B(X)	FFHT1614T*	FGHT1835S*	RC492704
ART348FFF***	BFBF2715GSIM	BRFB1822SSN	B36IT900NP	CRT12PHS2	DAR110A2*	RF 2105W	RF170B(X)	FFHT1621Q*	FGHT1837T*	<b>Gaggenau</b>
<b>Artic King</b>			<b>Bourdeau Professional</b>							<b>\$50</b>
<b>\$50</b>	BFBF2715SS	BRFB1900FBI	<b>Kitchen</b>	CRT12PHW2	DFF100C2BSLDD	RF1003ESW	RF170W*****	FFHT1621T*	FGHT1842T*	
ATMA100AEB	BFBF2715SSIM	BRFD2034SS	<b>\$50</b>	CRT151HQ*	DFF100C2BSSDD	RF1004ESBB	RS36(X)	FFHT1814Q*	FGHT1846Q*	RB280703
ATMA100AES	BFBF3018SS	BRFD2230SS	FB3601U	CRT182HQ*	DFF100C2WDD	RF1004ESSS	RS36A80	FFHT1814T*	FGHT2042T*	RB280704
ATMA100AEW	BFBF3018SSIM	BRFD2234SS	<b>Brigade</b>	CRT186HQ*	DFF101B1BSSDD	RF1802B	<b>Frigidaire</b>	FFHT1821Q*	FGHT2046Q*	RB472701
ATMA100AEW	BFBF3018SSIML	BRFD2650SSN	<b>\$50</b>	CRT206HQ*	DFF123C2BSSDD	RF1802SS	<b>\$50</b>	FFHT1821T*	FGHX2355T*	RB492701
ATMA115AEB	BFBF3018SSL	BRFD2652SS	CFBI7360****	CRTEH182T*	DFF123C2WDD	RF1802W	DGHD2361T*	FFHT1831Q*	FGHX2655T*	RY492701
ATMA115AES	BFFD3620SS	BRFT1522SS	CMVBI7360****	<b>Dacor</b>	<b>DCS</b>	<b>Emerald Cool</b>	DGHF2360P**A	FFHT1832T*	FPHB2899P*	RY492701TW
ATMA115AEW	BFFD3622SS	G91631NELU	CVBI7360****	<b>\$75</b>	<b>\$50</b>	<b>\$50</b>	DGHK2355T*	FFHT2021Q*	FPHB2899P**A	RY492704
<b>Avanti</b>	BFFD3624SS	K60310HU	<b>CLASSIC</b>	DRF36750***	RS36(X)	RF 1203ESSS	DGHX2355T*	FFHT2021T*	FPHG2399P**A	<b>Gallery</b>
<b>\$50</b>	BFFD3626SS	K74505NU	<b>\$50</b>	DRF36C100**	RS36A80	RF1003 ESW	DGHX2655T*	FFHT2032T*	FPHS2399P**A	<b>\$50</b>
FF116B0W	BFTF2715SSIM	K76540NEBU	3760-912	DRR24980***	<b>Electrolux</b>	RF1004ESBB	DGUS2645L**A	FFHT2131Q*	FPHS2699P**A	FGVU17F8QF*
FF116B1B	BRFD2030SS	<b>Blomberg &amp; Beko</b>	3760-913	DRR30980***	<b>\$50</b>	RF1004ESSS	FDBC2250S*	FFHX2325T*	FPHT1897T*	FGVU17F8QT*
FF116B3S	<b>Beko &amp; Blomberg</b>	<b>\$50</b>	MDRF375WE	DRR30990***	EI11BF25Q5	RF1203ESSS	FDBG2250S*	FGEB28D7R*	FPHT18D3R*	FGVU21F8QF*
FF116D0W	<b>\$50</b>	K76540NEBWU	<b>Conserv</b>	DRR36980***	EI23BC30K**A	RF1203ESW	FDBN2750S*	FGEX2631Q*	LAVZ2636T*	FGVU21F8QT*
FF21D0W	K60340N	<b>Bluestar</b>	<b>\$75</b>	DRR36980***	EI23BC32S*	RF1203ESW	FDBS2750S*	FGHB2866P*	LFHB2741P**A	<b>GE</b>
FF21D1B	<b>Bertazzoni</b>	MDRF375WED	<b>\$50</b>	MDRF375WE	EI23BC35K**A	RF1802B	FFET1022Q*	FGHB2866P**A	LFHB2751T*	<b>\$50</b>
FF21D3S	<b>\$50</b>	MDRF375WED	<b>Crosley</b>	<b>\$50</b>	EI23BC37S*	RF1802SS	FFET1022UB	FGHB2867T*	LFHD2251T*	DFE28JBL****
FF99D0W	REF24BMX	DRF42750***	<b>Bosch</b>	DRF42750***	EI23BC60K**A	RF1802W	FFET1022US	FGHB2868T*	LFHG2251T*	DFE28JEL****
FF99D3S	REF31BMXR	DTF24BFP	<b>\$75</b>	DTF24BFP	EI23BC65K**A	<b>EuroDesign</b>	FFET1022UW	FGHC2355PF*C	LFHT1831Q*	DFE28JGH****
FFBM102D0W	REF31BMXL	DTF36FCS	B10CB80NVB	DTF36FCS	EI26SS30J**A	<b>\$50</b>	FFET1222Q*	FGHD2368T*	LFHT2131Q*	DFE28JMH****
FFBM102D2P	<b>Blomberg</b>	DYF42BSIWS	B10CB80NVS	DYF42BSIWS	EI28BS56S**A	EDR085S	FFET1222UB	FGHF2366P**A	LGHB2867P*	DFE28JMK****
FFBM102D3S	<b>\$50</b>	DYF42SBIW*	B10CB80NVV/01	DYF42SBIW*	<b>ELLIPSE</b>	EDRTM101SE	FFET1222US	FGHF2367T*	LGHB2867P**A	DFE28JSH****
FFBM92H*	7295745710	RF36NDFSS*	B11CB50SSS/01	RF36NDFSS*	<b>\$50</b>	EDRTM101WE	FFET1222UW	FGHG2366P**A	LGHB2867T*	DFE28JSK****
FFBM92HOW	BRFB1042SLN	<b>Daewoo</b>	B30B8930SS	EDRT180S	EDRT180S	EDRTM116SE	FGHG2367T*	FGHG2367T*	LGHB2869T*	DSE25JBL****
FFBM92H3S	BRFB1042SSN	<b>\$50</b>	B30I8900SP	EDRT180W	EDRT180W	EDRTM116WE	FGHG2368T*	FGHG2368T*	LGHD2369T*	DSE25JEM****
<b>AVG</b>	BRFB1042WHN	FR-1020ARS	B30I8900SP	ERBM010W	ERBM010W	<b>Fagor</b>	FGHI1864Q*	FGHI1864Q*	LGKH2336T*	DSE25JGH****
<b>\$50</b>	BRFB1051FFBIN	FR-1020ARW	B30I8900SP	ERBM104S	ERBM104S	<b>\$50</b>	LGHT1846Q*	LGHT1846Q*	LGHT1846Q*	DSE25JMH****
ARTM101SE	BRFB1052FFBIN	<b>Danby</b>	CRHH10RS	ERBM104W	ERBM104W	BMF-200X	LGHT2046Q*	LGHT2046Q*	LGHT2046Q*	DSE25JSH****
ARTM101WE	BRFB1152SSN	<b>\$50</b>	CRHH10RW	ERT085W	ERT085W	BMF-300X	LGHX2636T*	LGHX2636T*	LGHT2046Q*	GBE10ESI****
ARTM116SE	BRFB1312SS	B09I880NSP	CRHH12RB	ERTM101SE	ERTM101SE	<b>Fisher &amp; Paykel</b>	FGHK2355T*	FGHK2355T*	LGHT1521Q*	GBE21AGK****
ARTM116WE	BRFB1322SS	B09I881NSP	CRHH12RS	ERTM101WE	ERTM101WE	<b>\$75</b>	FGHN2866P**A	FGHN2866P**A	LGHT1521Q*	GBE21ASK****
	BRFB1452SSN	B11CB81SSS/01	CRHH12RW	ERTM116SE	ERTM116SE	RF201A*****	FGHN2867T*	FGHN2867T*	<b>Gaggenau</b>	GBE21DGK****
	BRFB1512SS	B20CS30SNS	CRMH10PD	ERTM116WE	ERTM116WE	RS24S	FGHN2868T*	FGHN2868T*	<b>\$75</b>	GBE21DSK****
	BRFB1522SS	B26FT50SNS	CRMH10PW	ERTM180SE	ERTM180SE	RS30S	RB492704	RB492704	RC262701TW	GDE20GGH****
			CRMH12PD							
			CRMH12PS							
			CRMH12PW							

\$50 Specifications (≥7.75 cu ft). Must be ENERGY STAR Certified.


\$75 Specifications (≥7.75 cu ft). Energy use is 15% less than the minimum federal efficiency standard.



GDE20GMH****	GIE18GCH****	GSE25HBL****	ABE20EGH****	PFE28KMK****	PYE22PSK****	RF20N6**E/*	NS-RTM18WH7	2537044*41	7942*	KBFS22EC*	LMXS30786*	LFXS24663*
GDE20GSH****	GIE18GSH****	GSE25HEM****	ABE21DGK****	PFE28KSK****	<u>Gladiator</u>	RF20N6ASE	NS-RTM21BS8,	2537060*41	7946*	KBFS25EC*	LSXC22336*	LFXS26566*
GDE21DGK****	GIE18GTH****	GSE25HG****	<u>GE Café</u>	PFE28PBL****	\$50	RF26N1ASE	NS-RTM21SS7	2537062*41	7998#	KBLC36FTS**	LSXC22436*	LFXS26596*
GDE21DMK****	GIE18HGH****	GSE25HMH****	\$50	PFE28PEL****	GARF30FDGB**	RF26N1AWE	NS-RTM21WH7	5172*41*	7999#	KBLO36FTX**	<u>LG</u>	LFXS26973*
GDE21DSK****	GIE18HSH****	GSE25HSH****	CFE24SSK****	PFE28PMK****	<u>Gorenje</u>	RF26N1BSE	NS-RTM21WH7-C	5176****	970R4242*	KBLS19KC*	\$50	LFXS27466*
GDE21EGK****	GIE18ISH****	GTE15CTH****	CFE28TSH****	PFE28PSK****	\$50	<u>Hotpoint</u>	NS-UZ17XWH7	5182#	970R4243*	KBLS22KC*	LBC24360**	LFXS27566*
					\$50							
GDE21EMK****	GIE21GML****	GTE15NTH****	CFE28UEL****	PFE28RSH****	HS3862EF	NS-UZ21XWH7		5185#	970R4244*	KBRC36FTS**	LBN22370**	LFXS28566*
GDE21ESK****	GIE21GSH****	GTE16DTH****	CFE28USH****	PFH28PSH****	HTS2762F	<u>Jenn-Air</u>		5186#	970R4246*	KBRO36FTX**	LBNC10551*	LFXS28596*
GDE23GGH****	GIE21GTH****	GTE16GSH****	CNE25SSK****	PNE21KKG****	HZF3362E	HPE15BTH****		6935*	970R4264*	KBRS19KC*	LBNC12551*	LFXS28968*
GDE23GSH****	GIE21HSL****	GTE16GTH****	CWE23SSH****	PNE21KMK****	HZF3362G	HPE15BTM****		6936*	970R7240*	KBRS22KC*	LBNC15221*	LFXS29626*
GDE25EGK****	GNE21DGK****	GTE18CCH****	CYE22TSH****	PNE21KSK****	HZF3762E	<u>Ikea</u>	JB36NXFXLE**	6936*	970R7240*	KBRS22KC*	LBNC15221*	LFXS29626*
GDE25ESK****	GNE21DSK****	GTE18CTH****	CYE22UEL****	PNE21NGL****	ZOF2862E	\$75	JB36NXFXRE**	6938*	970R7242*	KBSD502ESS**	LDC22370**	LFXS29766*
GFE24JBL****	GNE21FMK****	GTE18ETH****	CYE22USH****	PNE21NML****	<u>Haier</u>	<u>Ikea</u>	JB36S5FX**A**	7131#	970R7243*	KBSD508ESS**	LDC24370**	LFXS30726*
GFE24JGK****	GNE21FSK****	GTE18GMH****	<u>GE Monogram</u>	PNE21NSL****	\$50	<u>Ikea</u>	JB36S5FX**A**	7132#	<u>KFN 14943 SD</u>	KBSD602ESS**	LDCS22220*	LFXS30766*
GFE24JMK****	GNE25DGK****	GTE18GSH****	\$50	PNE21NSL****	QNE27JBM****	\$50	JBRF*24IGX**	7160#	\$50	KBSD608EBS**	LDCS24223*	LFXS30786*
GFE24JSK****	GNE25DSK****	GTE18GTH****	ZIC30GNH****	PNE25JMK****	QNE27JSM****	QNE27JSM****	JBRF*30IGX**	7248#	KFN 14943 SD	KBSD608EBS**	LDNS22220*	LFXS30796*
GFE26GGH****	GNE25JGK****	GTE18IGH****	ZIC360NH****	PNE25JMK****	<u>Hanover</u>	IRT134FD*0*	JBRF*36IGX**	7249#	<u>Kitchen Aid</u>	KBSD612ESS**	LCF21776*	LFXS32726*
GFE26GGK****	GNE25JMK****	GTE18ISH****	ZICP360NH****	PNE25JMK****	\$50	IRT138FD*0*	JFC2089BE*	7303#	\$75	KBSD618ESS**	LCF21776**	LFXS32766*
GFE26GMH****	GNE25JSK****	GTE18ITH****	ZIC360NH****	PNE25NML****	<u>Heartland</u>	IX3HHGXSS*	JFX2597AE*	7305#	KBX104***	KBWV11NCSS	LCF22770**	LMNS14420*
GFE26GMK****	GNE27ESM****	GTE18LGH****	ZIR360NH****	PNE25NSL****	HANRT10C*	IX6HHEXDS*	JS42PPDUDE**	7306#	<u>Kitchen Aid</u>	KBWS19KC*	LCF24770**	LMXC23746*
GFE26GSH****	GNE27JGM****	GTE18LMH****	ZIRP360NH****	PSE25KBL****	HANRT12C*	IX7DDEXDS*	JS42SSDUDE**	7313#	\$50	KBWS22KC*	LCF24786**	LMXC23796*
GFE26GSK****	GNE27JMM****	GTE18LSH****	ZIRS360NH****	PSE25KBL****	<u>Heartland</u>	IX7DDEXGZ*	JS48PPDUDE**	7315#	KB*S19KC*	KFXS25RY*	LCF25776**	LMXS27626*
GFE26JBM****	GNE27JSM****	GTE21GML****	ZWE23ESH****	PSE25KBL****	HCTMR20A**	IX7HHEXDS*	JS48SSDUDE**	7316#	KB*S19KC*	KRBL102ESS**	LCF28768**	LMXS27676*
GFE26JEM****	GNE29GGH****	GTE21GSH****	ZWE23PSH****	PWE23KGD****	HCTMR20A**	<u>Insignia</u>	<u>Kenmore</u>	7401#	KB*S22KC*	KRBL109ESS**	LCFC22426*	LMXS27766*
GFE26JMM****	GNE29GKK****	GTE21GTH****	<u>GE Profile</u>	PWE23KGD****	HCTMR20A**	\$50	\$50	7402#	KB*S22KC*	KRBR102ESS**	LCFS22520*	LMXS28626*
GFE26JSM****	GNE29GMH****	GWE19JGL****	\$75	PWE23KMD****	<u>Hisense</u>	NS-RBM10BK8	NS-RBM10BK8	7403#	KBBL206EPA**	KRBR109ESS**	LCFS25426*	LMXS30746*
GFE28GBL****	GNE29GSH****	GWE19JML****	PFH28PSH****	PWE23KMK****	\$50	NS-RBM10WH7	NS-RBM10WH7	7404#	KBBL206ESS**	KRBR102E****	LCFS25663*	LMXS30756*
GFE28GEL****	GNE29GSH****	GWE19JSL****	<u>GE Profile</u>	PWE23KSD****	\$50	NS-RBM92*	NS-RBM92*	7405#	KBBL306EPA**	KRBR109E****	LCFS28768*	LMXS30776*
GFE28GGK****	GNE29GSK****	GYE18JBL****	\$50	PWE23KSK****	NS-RBM92BK9	NS-RBM92BK9	NS-RBM92BK9	7407#	KBBL306ESS**	KRFC300E****	LCFS31626*	LMXS30796*
GFE28GMK****	GPE12FGK****	GYE18JBL****	PDE21KKG****	PYE18HBL****	NS-RBM92WH9	NS-RBM92WH9	NS-RBM92WH9	7409#	KBRR206EPA**	KRFC604F****	LCF22786**	LNXC23726*
GFE28GSK****	GPE12FSK****	GYE18JML****	PDE21KMK****	PYE18HML****	NS-RFD26SS9	NS-RFD26SS9	NS-RFD26SS9	7410#	KBRR206ESS**	KRFF302E****	LCFS22520*	LPXS30886*
GFE28HGH****	GPE16DTH****	GYE18JSL****	PDE21KSK****	PYE18HSL****	NS-RFD26SS9-C	NS-RFD26SS9-C	NS-RFD26SS9-C	7411#	KBRR306EPA**	KRFF305E****	LCFS22520*	LNXS30866*
GFE28HMH****	GSE22ESH****	GYE22HBL****	PFE24HGL****	PYE22KBL****	NS-RTM10BK8	NS-RTM10BK8	NS-RTM10BK8	7430*	KBRR306ESS**	KRFF507H**0*	LCF21976**	LNXS30996*
GFE28HMK****	GSE22ETH****	GYE22HMK****	PFE24HML****	PYE22KEL****	NS-RTM10WH7	NS-RTM10WH7	NS-RTM10WH7	7431*	KBX104	KRSF505****	LCF28968*	LPXS34886*
GFE28HSH****	GSE23GGK****	GYE22HSK****	PFE24HSL****	PYE22KMK****	NS-RTM10WH7-C	NS-RTM10WH7-C	NS-RTM10WH7-C	7504#	KBFN402EPA**	KSSC42QVS**	LCF22526*	LPXS30866*
GFE28GSH****	GSE23GSK****	GYE22KMK****	PFE24JGK****	PYE22KSK****	NS-RTM12SS7	NS-RTM12SS7	NS-RTM12SS7	7505#	KBFN402ESS**	KSSC48QVS**	LCF22596*	LPXS30876*
GIE16DGH****	GSE25ESH****	GYE22KSH****	PFE24JMK****	PYE22PBL****	NS-RTM12SS7-C	NS-RTM12SS7-C	NS-RTM12SS7-C	7902#	KBFN502EBS**	<u>LG</u>	LCF24726*	LPXS30886*
GIE16GSH****	GSE25ETH****	<u>GE Artistry</u>	PFE24JSK****	PYE22PEL****	NS-RTM18BK8	NS-RTM18BK8	NS-RTM18BK8	7904#	KBFN502EPA**	\$75	LCF24766*	LSFD2491**
GIE18CTH****	GSE25GGH****	\$50	PFE28KBL****	PYE22PMK****	NS-RTM18BS8	NS-RTM18BS8	NS-RTM18BS8	7931***	KBFN502ESBOO**	LFX29937**	LCF24796*	LSFCX2476*
GIE18ETH****	GSE25GSH****	ABE20EGH****	PFE28KEL****	PYE22PSH****	RD-46WC1H*	RD-46WC1H*	RD-46WC1H*	7934***	KBFN502ESS**	LFXS32736*	LCF24623*	LSFCX2496*
					RF20N6**E,	NS-RTM18SS7-C	NS-RTM18SS7-C	7941*	KBFS20EC*	LMXS28636*	LFXS24626*	LSB2691**

\$50 Specifications (≥7.75 cu ft). Must be ENERGY STAR Certified.

\$75 Specifications (≥7.75 cu ft). Energy use is 15% less than the minimum federal efficiency standard.



LSSB2692**	HC 1541	HRB 1120	MFC2062FE**	HD-663FWEN(SZ)	KFNS37692IDE-1	RF22K9581**	RF34H9960**	IC-24R	T30IB9015P	FBI7360****	WRF954CIH***
LSSB2696**	HC 1550	R 1410	MFF2258DE*	HD-663W	KNF 12823 SD edt/cs-2	RF22KR*DB**	RH22H9010*	IC-30R**	T30IR8005P	FDSB5423*****	WRF992FIF***
LSXC22326*	HC 1551	RB 1410	MFF2258FE*	HD-774FW	KS 37472ID	RF22M9581**	RH25H5611**	IC-36R**	T30IR9005P	FDSB5483*****	WRF993FIF***
LSXC22386*	HC 2060	<b>Mabe</b>	MFF2558DE*	UR-BCD280WE-S	<b>MIGALI</b>	RF22N9781**	RH29H9000**	IT-30CI**	T30IR9015P	FRI7240****	WRF995FIF***
LSXC22396*	HC 2061	\$50	MFF2558FE**	UR-BCD326WE-S	\$50	RF22NP*DB**	RH30H9500**	IT-30R**	T36BB910SS	MVBI7360****	WRF995FIF***
LSXC22426*	HC 2062	MBE11D****	MFI2570FE**	WHD-366FWEB1	MH-18MA	RF23HC*DB**	RL225N*TA**	IT-36CI**	T36BB920SS	MVRI7240****	WRF995FIF***
LSXC22486*	HC 2080	MDU25EGK****	MFT2574DE*	WHD-366FWESS1	MH-18MA-B	RF23HC*DT**	RS22HD*PN**	IT-36R**	T36IB9005P	VBI7360****	WRR56X18F***
LSXS22423*	HC 2081	MDU25ESK****	MFT2772HE*O*	WHD-366FWEW1	<b>Moffat</b>	RF23HT*DB**	RS25H5111**	<b>Summit</b>	T36IR9005P	VCSB5423*****	WRS331FDD*O*
LSXS26386*	HC 2082	<b>Magic Chef</b>	MFT2776DE*	WHD-368RWESS1	\$50	RF23J9011**	RS25H5121**	\$50	T36IR9015P	VCSB5483*****	WRS331SDH*O*
LSXS26396*	HCB 1560	\$50	MFT2776FE**	WHD-368RWEW1	MBR12DGH****	RF23M8570**	RT18M61*4**	FF1084W	<b>Thermador</b>	VRI7240****	WRS335FDD***
LSXS26466*	HC 1561	HMDR1000BE	MFT2778EE**	WHD-663FWEB1	MBR12DSH****	RF23M8590**	RT18M62*3**	FF1085SS	\$50	<b>Whirlpool</b>	WRS335SDH*O*
LTC520120*	HC 2060	HMDR1000SE	<b>MicroFridge</b>	WHD-663FWESS1	MTE18G*****	RF24FS*DB**	RT18M62*5**	FF1118W	T30BB920SS	\$75	WRS586FID*
LTC520220*	HC 2061	HMDR1000ST	\$50	WHD-663FWEW1	MTE18H*****	RF24J9960**	RT21M62*3**	FF1119B	T36BT920NS	CB345W	WRS586FIE**
LTC524223*	HC 2062	HMDR1000WE	10.1MF1*	WHD-774FW1	<b>Monogram</b>	RF25HM*DB**	RT21M62*5**	FF1159SS	T36BT920NS	WRS551WNBS	WRS586FLD*
LTVS20220*	HC 2080	MCBM920S1	10.1MF1R	<b>Miele</b>	\$50	RF260B*AE**	<b>Signature Kitchen Suite</b>	FF11386W	T30BB810SS	<b>Whirlpool</b>	WRS975SID**
LUPXC2386*	HC 2081	MCBM920W1	10.3LMF4-9D1	\$75	ZIR240NBK****	RF261BEAE**	\$75	FF1387SS	T30BB820SS	\$50	WRT134TFD*O*
<b>LG Signature</b>	HC 2082	<b>Marathon</b>	10.3LMF4-9D1W	K1803 SF	ZIR240NPK****	RF265B*AE**	SKSCF2401*	FF1511SS	T30IB8005P	URB551WNGZ	WRT134TFD*O*
\$50	HC 2082	MCB1010WEF	10.3LMF4-9D1WX	K1803 Vi	ZIR300NBK****	RF26HF*ND**	SKSCF3001*	FF1512SSIM	T36BB810SS	WRB119WFB*	WRT138FZD*
LUPXS3186*	HC 2081	\$50	10.3LMF4-9D1X	K1813 Vi	ZIR300NPK****	RF26J7500**	SKSCR2401*	FFBF100W	T36BB820SS	T36BB820SS	WRT148FZD*
<b>Liebherr</b>	<b>Liebherr</b>	MAR86BLS	10.3LMF4-9TPWX	K1903 SF	<b>Panasonic</b>	RF28HD*DB**	SKSCR3001*	FFBF101SS	T36BT810NS	<b>Signature Kitchen Suite</b>	WRB322DMH*
\$75	\$50	MAR86W	10.3LMF4-9TPX	K1903 Vi	\$50	RF28HD*DT**	SKSCR3001*	FFBF181ES	T36BT820NS	WRB329*FB*	WRT348FME*O*
CBS 2062	BF 1061	MFF101*	10.3LMF4R	K1913 Vi	NR-D535XC	RF28HF*DT**	\$50	FFBF191SS	T36BT910NS	WRB329DMB*	WRT541SZH*O*
CBS1660	CBS1360	MFF101W	10.3LMF4RW	KFN 13823 D	<b>Samsung</b>	RF28HFEDB**	SKSFD3604*	FFBF192SS	T36IB8005P	WRF532SMB*	WRT549SZD*
CBS1661	CS 1200	MFF920*	10.3RMF4-9D1	KFN 15943 D	\$75	RF28HM*DB**	UPFXC2466*	FFBF240WX	T36IT800NP	WRF532SMB*	WRX735SDH*
CBS2082	CS 1311	MFF920WBM	10.3RMF4-9D1W	KFN 15943 DE	BRF36520**	RF28HM*LB**	UPSXB2627*	FFBF241W	T36IT900NP	WRF532SNB*	
CS 2060	CS 1350B	<b>Maytag</b>	10.3RMF4-9D1WX	KFN 9855IDE	RF23M8070**	RF28J8*DB**	<b>Smeg</b>	FFBF246SS	T36IT901NP	WRF532SNH*	
CS 2061	CS 1360	\$50	10.3RMF4-9D1X	KFN9955IDE	RF23M8090**	RF28K9070**	\$50	FFBF247SSIM	<b>THORKITCHEN</b>	WRF532SMB*	
CS 2062	CS 1400	MB*1957DE*	10.3RMF4-9TP	<b>Miele</b>	RF23M8960**	RF28K9380**	CB300U	FFBF249SS	\$50	WRF532SNB*	
CS1210	CS 1611	MBB1957DE*	10.3RMF4-9TPWX	\$50	RF263B*AE**	RF28K9580**	FTU171*7	FFBF281W	TKF3601U	WRF532SNH*	
CS1321	CS 1640	MBB1957FE**	10.3RMF4-9TPX	KF1803 SF	RF263T*AE**	RF28M9580**	FTU171X7	FFBF286SS	<b>True Residential</b>	WRF532SNH*	
CS1400PC	CS 1660	MBF1953DE*	10.3RMF4R	KF1803 Vi	RF26HFPNB**	RF28N9780**	<b>Sub-Zero</b>	FFBF287SSIM	\$50	WRF540CWB*	
CS1400R	CS1360B	MBF1958DE*	10.3RMF4RW	KF1813 SF	RF28HD*DP**	RF28N8*DB**	\$50	<b>Thermador</b>	TR-30REF-***.*	WRF540CWB*	
CS1400R-IM	HC 1021	MBF1958FE**	<b>Midea</b>	KF1813 Vi	RF28HFDPB**	RF30HB*DB**	BI-30U/S/**	TR-30REF-L-OP-A	TR-30REF-L-OP-A	WRF555SDF***	
CS1401R-IM	HC 1030	MBF2258DE*	\$50	KF1903 SF	RF28MFEDE**	RF30HD*DT**	BI-36R/*/**	T23IR9005P	TR-30REF-R-OP-A	WRF555SDH*	
CS1410	HC 1030 PC	MBF2258FE**	HD-366FWEN(SZ)	KF1903 Vi	RF28ND*DB**	RF30KM*DB**	BI-36U/S/**	T24IR8005P	TR-30REF-R-SS-A	WRF736SDA*	
CS1640B	HC 1050 PC	MBL1957DE*	HD-368RWES	KF1913 SF	RP22M3105**	RF31FM*DB**	BI-36UID/S/**	T24IR9005P	<b>Viking</b>	WRF757SDE***	
CS2080	HC 1050B	MBL1957FE**	HD-423FWEN(SZ)	KF1913 Vi	<b>Samsung</b>	RF31FM*SB**	BI-42S/S/**	T24IR9015P	\$50	WRF757SDH*O*	
CS2081	HC 1070	MBR1957DE*	HD-663FWE	KFN 13923 DE	\$50	RF323T*DB**	BI-48S/S/**	T30BB910SS	CFRI7240****	WRF767SDE***	
CS2082	HC 1080	MBR1957FE**	HD-663FWE(SZ)	KFN 14943 SDE	BRF42520**	RF32FM*DB**	IC-24C	T30BB920SS	CMVRI7240****	WRF767SDH*O*	
HC 1540	HC 1060	MFC2062DEM*	HD-663FWEN	KFN37232ID	RF22K9381**	RF34H9950**	IC-24CI	T30IB9005P	CVRI7240****	WRF9*4CIH***	

\$50 Specifications (≥7.75 cu ft). Must be ENERGY STAR Certified.

\$75 Specifications (≥7.75 cu ft). Energy use is 15% less than the minimum federal efficiency standard.